

Firmware: Web-Thermometer Air Quality Model 57718

Current firmware

Date	Changes and comments	Revision
January 9,	Stability improvements	1.69
2024	HTTP requests with token authentication optimized	ZIP download
	Self-signed certificate for OPC UA use optimized	
	Measuring module: System start optimized	
	Error fixed: Mail authentication method Auth failed	
	Please be sure the device has at least Version 1.08 before the update!	

Older firmware

Date	Changes and comments	Revision
August 23, 2023	 TCP/IP stack - MTU up to max. 1500 possible Actions - Host name for HTTP requests in the head corrected HTTP(S) - POST for actions added Measuring module communication revised Error fixed: MQTT standard messages erroneous Please be sure the device has at least Version 1.08 before the update!	1.67 ZIP download
January 16, 2023	 Update procedure optimized Fixed: Problem with file uploading for certificates fixed Sensor communication optimized Please be sure the device has at least Version 1.08 before the update!	1.65 ZIP download
November 8, 2022	 Error fixed: At special relative humidity values a "Sensor lost" message was generated. Input screen for mail server revised DHCP - Processing of the option flags expanded OPC UA - Transfer of application URI corrected Please be sure the device has at least Version 1.08 before the update!	1.63 ZIP download
August 9, 2022	 Error fixed: Turning on the OPC UA caused permanent reset which could only be resolved by a factory reset. Security: Eliminating the outdated protocols TLS 1.0 and 1.1. Effective immediately only TLS 1.2 is supported. Please be sure the device has at least Version 1.08 before the update!	1.59 ZIP download
July 12, 2022	• File upload optimized Please be sure the device has at least Version 1.08 before the update!	1.58 ZIP download
May 4, 2022	 New: Configure measurement value compensation with up to 10 correction points per sensor via JSON file. Firmware update: Initiating via button in the interface possible Please be sure the device has at least Version 1.08 before the update! 	1.57 ZIP download
March 2, 2022	 New: Configurable NodeIDs for OPC-UA MQTT: Retain flags revised Please be sure the device has at least Version 1.08 before the update! 	1.55 ZIP download

Date	Changes and comments	Revision
January 20, 2022	 HTTPS - Chunked transfer revised SSL/TLS - Certificate upload now possible again DHCP - IP assignment with DHCP relays adapted Boot sector - Emergency access when firmware update is interrupted now revised 	1.54 ZIP download
	Please be sure the device has at least Version 1.08 before the update!	
December 16, 2021	 Security updates: DHCP, DNS and ICMP services revised Error in SNMP output corrected Erroneous output in MQTT corrected 	1.53 ZIP download
	Please be sure the device has at least Version 1.08 before the update!	
August 5, 2021	Problem fixed: Wrong time stamp was entered for the first value in the data logger.	1.51 ZIP download
	Please be sure the device has at least Version 1.08 before the update!	
June 22, 2021	Problems in SNMPv2/3 MIB tree fixed Problems in cloud communication fixed	1.50 ZIP download
	Please be sure the device has at least Version 1.08 before the update!	
May 20, 2021	 Error fixed: SNMP output with different decimal points Measuring module software updated and restart improved 	1.49 ZIP download
	Please be sure the device has at least Version 1.08 before the update!	
May 3, 2021	 New: OPC UA support New: Uploading of your own certificates New: Subsequent delivery of historical data via MQTT Error messages for MQTT connections added Web-API polling revised Web server error messages optimized HTTP processing revised REST connections revised Security updates 	1.48 ZIP download
	Please be sure the device has at least Version 1.08 before the update!	
September 15, 2020	 Error fixed: When uploading the configuration file to the device SNMP passwords were not accepted Automatic monitoring for measuring module failure added Firmware update for measuring module revised 	1.46 ZIP download
	Please be sure the device has at least Version 1.08 before the update!	
August 17, 2020	TLS: Problems with TLS handshake fixedFactory default reset could fail	1.45 ZIP download
	Please be sure the device has at least Version 1.08 before the update!	
July 21, 2020	 TLS: Support of TLS 1.2 Server authentication revised Character coding for HTTP request message corrected Detection of incomplete OPC requests implemented SNMP index error when generating dynamic names corrected System start optimized Up-Time control for the measuring model added Assignment of the device error list revised 	1.44 ZIP download
	Please be sure the device has at least Version 1.08 before the update!	

Date	Changes and comments	Revision
March 2, 2020	Problem in OPC communication fixed	1.40
,	Problem with SNMP name indexing fixed	ZIP download
	Transmission problems with sensor extension fixed	
	Please be sure the device has at least Version 1.08 before the update!	
January 31,	Network stack optimized	1.39
2020	Diagnostics list corrected	ZIP download
	Configuration upload accelerated	
	Addition of SSL for MQTT connections MQTT Client-ID now freely configurable	
	authentication mechanism stabilized	
	OPC communication optimized	
	DHCP functionality stabilized	
	Problem fixed: Error in device interface	
	 Problem fixed: Error in SNMPv3 authentication Problem fixed: Error in timed alarms when time is entered manually 	
	 Problem fixed: Error in MQTT authentication 	
	Please be sure the device has at least Version 1.08 before the update!	
November 28, 2019	Problem fixed: Zoom error in visualizationProblem fixed: Cloud output with deselected sensors failed	1.36 ZIP download
2019	Froblem fixed. Cloud output with deselected sensors failed	ZIF download
	Please be sure the device has at least Version 1.08 before the update!	
September 30,	MQTT topics may now contain W&T tags	1.35
2019	Passwords can now be set by uploading the configuration file. Problem fixed: After remainer the concert the last measured values remain	ZIP download
	 Problem fixed: After removing the sensor the last measured values remain available. 	
	 Problem in SNMPv3 could have caused a "NotInTimeWindow" error. 	
	Problem with REST Digest Authentication fixed.	
	Please be sure the device has at least Version 1.08 before the update!	
August 6, 2019	Problems with factory default reset fixed.	1.34
	Problems with MQTT ping interval fixed.	ZIP download
	 Problem fixed: MQTT Retain Flag was sometimes not set. Problem fixed: Alarm Clear message with an Index > 12 alarms was incorrectly 	
	sent.	
	Problems with SNMPv3 module type detection fixed.	
	Possible problems with software reset fixed.	
	Possible calculation error with negative numbers fixed.	
	Possible log in problems when using certain mail server fixed.Fall-back system for ensuring configuration integrity after firmware update	
	improved.	
	MQTT standard paths added.	
	Device registration reserved only for the administrator user.	
	Please be sure the device has at least Version 1.08 before the update!	
May 6, 2019	Fixed: Uploading of large configuration files failed.	1.32
way 0, 2019	 Fixed: CP client message was sometimes not initiated. 	ZIP download
	Fixed: Error in SSL stack eliminated.	
	Script components updated	

Date	Changes and comments	Revision
March 26, 2019	New: Supports Modbus-TCP for measurement value polling	1.31
	 New: SNMPv2 and SNMPv3 supported 	ZIP download
	Problem with zoom function fixed.	
	Fixed: LED in sensor was always red.	
	Fixed: No display of measurement values when using replaceable tags in HTTP request measurement.	
	request message.Fixed: Units not output when sensor turned off.	
	 Fixed: Only output when sensor turned on. Fixed: Restart after software reset was able to be interrupted. 	
	Please be sure the device has at least Version 1.08 before the update!	
December 13,	Cloud communication optimized.	1.30
2018	FTP data output optimized.	ZIP download
	WuTility inventorying problem fixed.	
	Problem fixed: Interval selection for data retention output was not accounted	
	for. Problem fixed: MQTT connection opening after closing the connection was not 	
	reinitiated.	
	Problem fixed: Value output in visualization failed if sensor names included	
	special characters.	
	Web-API - Cross Origin Request can be configured.	
	Rest - Cross Origin Request can be configured.	
	Please be sure the device has at least Version 1.08 before the update!	
May 30, 2018	Problem fixed: Output problems with CSV logger file fixed.	1.27
	Problem fixed: Special characters in device visualization were not correctly	ZIP download
	processed.	
	Problem fixed: Text fields for server addresses were too short for alphanumeric	
	entries.	
	Problem fixed: SNMP system messages were not sent.	
	Please be sure the device has at least Version 1.08 before the update!	
May 8, 2018	Problem fixed: A "Sensor lost" message was not triggered for certain	1.22
	configuration constellations.	ZIP download
	Please be sure the device has at least Version 1.08 before the update!	
March 6, 2018	Problems with MQTT data transfer fixed	1.20
	TCP client handling revised	ZIP download
	W&T cloud data transmission optimized	
	Problem fixed: SNMP trap texts were not output	
December 14,	MQTT Publish: QoS can be set	1.16
2017	MQTT Publish: Retain can be set	ZIP download
	MQTT Publish: Last Will can be set	
	MQTT Publish: Message can be set for Connect	
	 Measurement value transmission to W&T cloud revised 	
	Functionality change: New passwords may not contain '&'	
November 29,	Problems with TLS connection fixed	1.15
2017	Problems in saving the DNS server fixed Eived: Output problem that could occur if not all concern were collected for data	ZIP download
	 Fixed: Output problem that could occur if not all sensors were selected for data logging 	
	 Problem when changing from DHCP to static IP address fixed 	
	 Problem in configuring the sensor compensation fixed 	
	Certificate problem with HTTPS connections in Chrome browser fixed	
July 7, 2017	Error in cloud access fixed	1.14
ouly 7, 2017		ZIP download

Date	Changes and comments	Revision
June 28, 2017	 Configuration up/download limited to Administrator level users Speed optimizations for browser communication 	1.13 ZIP download
	 Errors in color selection fields fixed Error in internal matching of network settings and system ports fixed 	
	DHCP client revised	
	MTU error in TCP stack fixed MQTT: Unique Client-ID for connection opening added	
	MQTT: Messages without topic and message text prevented	
March 20, 2017	New: Web access via encrypted HTTPS- Connection added	1.12
	New: Test message revision. The selected reporting path is triggered exactly once. No reset.	ZIP download
	New: Data sending via MQTT added. New: Access via REST added.	
	• New: All system and service ports can be changed/turned off separately.	
	 New: Introduction of the port list for the overview of open and closed network ports. 	
	 New: Reverse function for monitoring the area within the alarm limits added. New: Function for hiding the menu tree added. 	
	New: Introduction of Web-API and socket-API for separating the access ports	
	for measurement value query.Problem with "Sensor lost" message fixed. No sensor was able to be selected.	
	 Data transmission rate and device performance improved. 	
	Note! When downgrading to version 1.12 you will then have to perform a reset to factory default settings using the internal jumper.	
	If you are querying this device using socket commands (e.g. GET /Single) or HTTP requests, please note the following changes implemented in firmware V1.12 and higher.	
	Due to the incremental introduction of a modern security concept into the device software, it is in this exceptional case unfortunately not possible to offer 100% compatibility with previous firmware versions.	
	Use of the query commands, without a preceding HTTP header, is now implemented using two separate services:	
	 Socket-API: Query commands without preceding HTTP header Web-API: Query commands as HTTP request with preceding HTTP header 	
	To make these services configurable independently of each other and capable of being turned off individually, various network ports are necessary. Whereas use of the Web-API remains as before on the configured HTTP port , now for the socket-API the (configurable) port 42280 is preset.	
	Use of both services on the same port as used to be the case is now no longer possible. These two query services are disabled by default in firmware V1.12 and higher.	
	If your application queries the device using HTTP requests, create the function as follows:	
	Enable in the menu under Communication paths >> Web-API >> Allow HTTP requests >> enabled	
	If your application queries the device using a socket command, create the function as follows:	
	Enable in the menu under Communication paths >> Socket-API >> TCP ASCII- Sockets >> enabled	
	Note that you must also change the TCP port used to the port configured here (Default: 42280) in your application. If this is not possible, you can also change the HTTP port in the device network settings so that port 80 can be used for the socket API.	
	Due to replacement of script files, problems with display of the homepage can occur after the update. To resolve this you must simply clear your browser cache and reload the page .	

Date	Changes and comments	Revision
September 15, 2016	 Problem with the select box for selecting mail encryption fixed. Problem with access via UDP fixed. Visual corrections in the configuration menu Spelling mistakes corrected Due to replacement of script files, problems with display of the homepage can occur after the update. To resolve this you must simply clear your browser cache and reload the page.	1.09 ZIP download
July 5, 2016	 Fixed: DHCP, incorrect display of the lease time corrected Fixed: DHCP, requests were sometimes sent with the wrong checksum Fixed: Display of the temperature in Fahrenheit and Kelvin corrected Fixed: Deleting your own Web page when updating firmware prevented Fixed: Output error in your own Web page corrected Upload button for Web pages removed (function is part of the Apply button) Info icon exchanged Mail authentication is now selected using a select box Due to replacement of script files, problems with display of the homepage can occur after the update. To resolve this you must simply clear your browser cache and reload the page.	1.08 ZIP download
March 16, 2016	 Error fixed: Standard values for factory default settings corrected Error fixed: Changed system name was not applied for DHCP requests Error fixed: Time synchronization with measuring interval (possible missing measurement values in the logger) Error fixed: Correct function of the delay time for message sending ensured Optimized use of the browser cache Optimizing of the session ID (128-bit value) Optimizing of display of the device Web pages New: Ability to display an analog clock and a calendar page on the homepage Due to replacement of script files, problems with display of the homepage can occur after the update. To resolve this you must simply clear your browser cache and reload the page. 	1.07 ZIP download
February 9, 2016	First firmware version	1.06 ZIP download



We are available to you in person:

Wiesemann & Theis GmbH Porschestr. 12 42279 Wuppertal Phone: +49 202/2680-110 (Mon.-Fri. 8 a.m. to 5 p.m.) Fax: +49 202/2680-265 info@wut.de

© Wiesemann & Theis GmbH, subject to mistakes and changes: Since we can make mistakes, none of our statements should be applied without verification. Please let us know of any errors or misunderstandings you find so that we can become aware of and eliminate them.

Data Privacy