

Firmware:

USB-Server Industry

Model 53641

Current firmware

Date	Changes and comments	Revision
July 14, 2011	<ul style="list-style-type: none"> Optimized: Plug & play behavior Fixed: DataToggle problem Optimized: Bulk transfer <p>Firmware 2.61 must only be used with USB Redirector > 1.90. Download The current configuration of the USB-Server is <i>not</i> affected by a firmware upgrade.</p>	2.61 ZIP Download

Older firmware

Date	Changes and comments	Revision
June 6, 2011	<ul style="list-style-type: none"> Optimized: Buffer overrun detection Fixed: Display problems with Internet Explorer Fixed: Bulk packet loss <p>Firmware 2.60 must only be used with USB Redirector > 1.84 Download</p>	2.60 auf Anfrage
March 2, 2011	<ul style="list-style-type: none"> USB driver optimized Optimized: Passwords with special characters Optimized: Devices with Alternate Setting Optimized: Speed increased <p>Firmware 2.56 must only be used with USB Redirector > 1.70 Download</p>	2.56 auf Anfrage
November 18, 2010	<ul style="list-style-type: none"> New: Devices can be copied from another PC USB driver optimized Web page corrected <p>Firmware 2.52 must only be used with USB Redirector > 1.70 !!! Download</p>	2.52 auf Anfrage
October 21, 2010	<ul style="list-style-type: none"> Bulk transfer optimized System name and device description can be configured on the web page USB device list corrected (web page) <p>Firmware 2.50 must only be used with USB Redirector > 1.51 !!! Download</p>	2.50 auf Anfrage
July 21, 2010	<ul style="list-style-type: none"> Connect LED function optimized Assigning IP address 0.0.0.0 is caught 0-byte In-Requests are now correctly answered <p>Firmware 2.30 must only be used with USB Redirector > 1.51 !!! Download</p>	2.30 auf Anfrage
02.06.2010	<ul style="list-style-type: none"> Speed optimized Error fixed with large USB packets Display error for IP addresses fixed Compatible with Siemens MPI adapter <p>Firmware 2.26 must only be used with USB Redirector > 1.44 !!! Download</p>	2.26 auf Anfrage
January 31, 2010	<ul style="list-style-type: none"> The first plug-in no longer causes a communication problem Plug/unplug events for both ports optimized Not set network addresses are caught All unneeded services are turned off at an update 	2.03 auf Anfrage
January 29, 2010	<ul style="list-style-type: none"> Password protection for configuration added 	1.36 auf Anfrage
January 22, 2010	<ul style="list-style-type: none"> Web-Based-Management fully implemented USB-Server process improved 	1.34 auf Anfrage

Wiesemann & Theis
GmbH
Porschestra. 12
42279 Wuppertal
Phone: +49 202/2680-110 (Mon.-Fri. 8 a.m. to 5
p.m.)
Fax: +49 202/2680-265
info@wut.de

© Wiesemann & Theis GmbH, subject to mistakes and changes: Since we can make mistakes, none of our statements should be applied without verification. Please let us know of any errors or misunderstandings you find so that we can become aware of and eliminate them.

[Data Privacy](#)