

Firmware:

**USB-Server Industry****Model 53641****Current firmware**

Date	Changes and comments	Revision
July 14, 2011	<ul style="list-style-type: none"> <li>Optimized: Plug &amp; play behavior</li> <li>Fixed: DataToggle problem</li> <li>Optimized: Bulk transfer</li> </ul> <p><b>Firmware 2.61 must only be used with USB Redirector &gt; 1.90.</b> <a href="#">Download</a> The current configuration of the USB-Server is <i>not</i> affected by a firmware upgrade.</p>	<p>2.61 <a href="#">ZIP download</a></p>

**Older firmware**

Date	Changes and comments	Revision
June 6, 2011	<ul style="list-style-type: none"> <li>Optimized: Buffer overrun detection</li> <li>Fixed: Display problems with Internet Explorer</li> <li>Fixed: Bulk packet loss</li> </ul> <p><b>Firmware 2.60 must only be used with USB Redirector &gt; 1.84</b> <a href="#">Download</a></p>	<p>2.60 on request</p>
March 2, 2011	<ul style="list-style-type: none"> <li>USB driver optimized</li> <li>Optimized: Passwords with special characters</li> <li>Optimized: Devices with Alternate Setting</li> <li>Optimized: Speed increased</li> </ul> <p><b>Firmware 2.56 must only be used with USB Redirector &gt; 1.70</b> <a href="#">Download</a></p>	<p>2.56 on request</p>
November 18, 2010	<ul style="list-style-type: none"> <li>New: Devices can be copied from another PC</li> <li>USB driver optimized</li> <li>Web page corrected</li> </ul> <p><b>Firmware 2.52 must only be used with USB Redirector &gt; 1.70 !!!</b> <a href="#">Download</a></p>	<p>2.52 on request</p>
October 21, 2010	<ul style="list-style-type: none"> <li>Bulk transfer optimized</li> <li>System name and device description can be configured on the web page</li> <li>USB device list corrected (web page)</li> </ul> <p><b>Firmware 2.50 must only be used with USB Redirector &gt; 1.51 !!!</b> <a href="#">Download</a></p>	<p>2.50 on request</p>
July 21, 2010	<ul style="list-style-type: none"> <li>Connect LED function optimized</li> <li>Assigning IP address 0.0.0.0 is caught</li> <li>0-byte In-Requests are now correctly answered</li> </ul> <p><b>Firmware 2.30 must only be used with USB Redirector &gt; 1.51 !!!</b> <a href="#">Download</a></p>	<p>2.30 on request</p>
02.06.2010	<ul style="list-style-type: none"> <li>Speed optimized</li> <li>Error fixed with large USB packets</li> <li>Display error for IP addresses fixed</li> <li>Compatible with Siemens MPI adapter</li> </ul> <p><b>Firmware 2.26 must only be used with USB Redirector &gt; 1.44 !!!</b> <a href="#">Download</a></p>	<p>2.26 on request</p>
January 31, 2010	<ul style="list-style-type: none"> <li>The first plug-in no longer causes a communication problem</li> <li>Plug/unplug events for both ports optimized</li> <li>Not set network addresses are caught</li> <li>All unneeded services are turned off at an update</li> </ul>	<p>2.03 on request</p>

Date	Changes and comments	Revision
January 29, 2010	<ul style="list-style-type: none"><li>• Password protection for configuration added</li></ul>	1.36 on request
January 22, 2010	<ul style="list-style-type: none"><li>• Web-Based-Management fully implemented</li><li>• USB-Server process improved</li></ul>	1.34 on request



[We are available to you in person:](#)

Wiesemann & Theis GmbH  
Porschestra. 12  
42279 Wuppertal  
Phone: +49 202/2680-110 (Mon.-Fri. 8 a.m. to 5 p.m.)  
Fax: +49 202/2680-265  
[info@wut.de](mailto:info@wut.de)

© Wiesemann & Theis GmbH, subject to mistakes and changes: Since we can make mistakes, none of our statements should be applied without verification. Please let us know of any errors or misunderstandings you find so that we can become aware of and eliminate them.

[Data Privacy](#)