

Firmware:

Web-IO Digital 2xIn, 2xOut

Model 57633

Current firmware

| Date | Changes and comments | Revision |
|---------------------|---|---|
| February 6, 2018 | <ul style="list-style-type: none"> Network buffer management revised <p>To load this firmware, WuTility must be used in the newest version included!</p> | <p>2.33</p> <p>ZIP download</p> |

Older firmware

| Date | Changes and comments | Revision |
|-----------------------|---|-------------------------------|
| January 8, 2016 | <ul style="list-style-type: none"> Boot-up behavior optimized <p>To load this firmware, WuTility must be used in the newest version included!</p> | <p>2.28</p> <p>on request</p> |
| September 29, 2010 | <ul style="list-style-type: none"> Problems with APP page eliminated <p>To load this firmware, WuTility must be used in the newest version included!</p> | <p>2.25</p> <p>on request</p> |
| August 19, 2010 | <ul style="list-style-type: none"> Box-to-Box - address management for NAT routing adjusted Login for binary access revised <p>To load this firmware, WuTility must be used in the newest version included!</p> | <p>2.24</p> <p>on request</p> |
| February 5, 2010 | <ul style="list-style-type: none"> Update procedure changed UDP - network buffer expanded UDP - remote port can be set as desired Negative logic for outputs configurable State=TOGGLE introduced for socket command outputaces DHCP: Device Name = DHCP Name <p>To load this firmware, WuTility must be used in the newest version included!</p> | <p>2.23</p> <p>on request</p> |