

Firmware:

LAN modem, 10/100BT, 24V**Model 58620****Firmware packet (TCP/IP stack + modem interpreter)****Current firmware**

Date	Changes and comments	Revision
January 25, 2011	<ul style="list-style-type: none"> • Modem-Interpreter = 1.14 • Support for fragmented UDP/IP packets • Optimizing of firmware upload in noisy environments <p>The newest included version of WuTility must be used for sending this firmware! The instructions for updating the individual firmware components are found in the associated manual.</p>	<p>2.11 ZIP download</p>

Older firmware

Date	Changes and comments	Revision
February 9, 2010	<ul style="list-style-type: none"> • Modem-Interpreter = 1.14 • Optimized handling when used with WuTility • Revised manual • Factory changed settings: <ul style="list-style-type: none"> ◦ Keep-Alive check = 5s ◦ Control port deactivated <p>The instructions for updating the individual firmware components are found in the associated Manual.</p>	<p>2.10 on request</p>