

Firmware:

Com-Server Highspeed 100BaseFX

Model 58651

Current firmware

Date	Changes and comments	Revision
November 11, 2022	<ul style="list-style-type: none"> Security update: WBM session management (VDE-2022-057) DHCP: Problem with DHCP relays corrected 	1.78 ZIP download

Older firmware

Date	Changes and comments	Revision
March 4, 2021	<ul style="list-style-type: none"> Security updates 	1.77 ZIP download
July 29, 2019	<ul style="list-style-type: none"> Fixed possibly critical weaknesses in Web Based Management (VDE-2022-043) DHCP problem with lease time "forever" fixed Corrections in SLIP mode 	1.76 ZIP download
April 30, 2015	<ul style="list-style-type: none"> Corrected: Closing a TCP connection for handshake stop condition and pending send data Corrected: DHCP for unstable links during the boot phase <p>The newest included version of WuTility must be used for sending this firmware!</p>	1.73 ZIP download
January 8, 2015	<ul style="list-style-type: none"> FTP server mode: Irregular connection closing by client allowed for SNMP was deactivated after update to 1.71 <p>The newest included version of WuTility must be used for sending this firmware!</p>	1.72 ZIP download
July 10, 2014	<ul style="list-style-type: none"> Web pages optimized for IE10 Box-to-Box: Dispatch Char in slave activated SLIP mode optimized DHCP: Optimized for high data load <p>The newest included version of WuTility must be used for sending this firmware!</p>	1.71 ZIP download
21.01.2011	<ul style="list-style-type: none"> Optimizing of firmware upload in noisy environments <p>The newest included version of WuTility must be used for sending this firmware!</p>	1.67 ZIP download
December 22, 2010	<ul style="list-style-type: none"> Support for fragmented UDP/IP packets Web Based Management optimized 	1.66 ZIP download
January 11, 2010	<ul style="list-style-type: none"> Keep-alive response in Box-to-Box mode modified Minimum length of Ethernet frames adjusted Reset behavior in DHCP mode revised 	1.64 ZIP download
May 4, 2009	<ul style="list-style-type: none"> Optimized DHCP response after link interruption SNMP correction incl. new MIB 1.23 Freely configurable baud rate divisor corrected IP bus mode corrected 	1.62 ZIP download
March 3, 2008	<ul style="list-style-type: none"> Base version 	1.59 ZIP download

We are available to you in person:

Wiesemann & Theis GmbH
Porschestra. 12
42279 Wuppertal
Phone: +49 202/2680-110 (Mon.-Fri. 8 a.m. to 5 p.m.)
Fax: +49 202/2680-265
info@wut.de

© Wiesemann & Theis GmbH, subject to mistakes and changes: Since we can make mistakes, none of our statements should be applied without verification. Please let us know of any errors or misunderstandings you find so that we can become aware of and eliminate them.

[Data Privacy](#)