

Firmware:

Com-Server 20mA

Model 58664

Current firmware

Date	Changes and comments	Revision
January 25, 2022	<ul style="list-style-type: none">Client modes: Behavior of the Disconnect-Char correctedDHCP: Problem with DHCP relays correctedTCP: Behavior of TCP-Zero-Window optimized <p>Updates for Com-Servers with versions older than 1.52 to versions 1.53 and higher are only possible if first an intermediate update to version 1.52 is uploaded.</p>	1.56 ZIP download

[Show older firmware...](#)



We are available to you in person:

Wiesemann & Theis
GmbH
Porschestra. 12
42279 Wuppertal
Phone: +49 202/2680-110 (Mon.-Fri. 8 a.m. to 5 p.m.)
Fax: +49 202/2680-265
info@wut.de

© Wiesemann & Theis GmbH, subject to mistakes and changes: Since we can make mistakes, none of our statements should be applied without verification. Please let us know of any errors or misunderstandings you find so that we can become aware of and eliminate them.

[Data Privacy](#)