

Firmware:

## Com-Server++ Model 58665

Date	Changes and comments	Revision
January 10, 2024	<ul> <li>NEW: Operating mode Modbus/TCP-Gateway (connecting MB/RTU slaves to MB/TCP masters)</li> <li>DHCP: Problem with custom DHCP options fixed</li> </ul>	1.58 ZIP download
	Updates for Com-Servers with versions older than 1.52 to versions 1.53 and higher are only possible if first an intermediate update to version 1.52 is uploaded.	

## Older firmware

Date	Changes and comments	Revision
January 25, 2022	<ul> <li>Client modes: Behavior of the Disconnect-Char corrected</li> <li>DHCP: Problem with DHCP relays corrected</li> <li>TCP: Behavior of TCP-Zero-Window optimized</li> <li>Updates for Com-Servers with versions older than 1.52 to versions 1.53 and higher</li> </ul>	1.56 on request
December 2, 2021	<ul> <li>are only possible if first an intermediate update to version 1.52 is uploaded.</li> <li>Security updates: WBM session management (VDE-2022-057)</li> <li>NEW: TCP Client mode with optional TLS-PSK encryption</li> <li>"Encrypted COM redirector" menu moved to "TCP Server" menu</li> <li>Updates for Com-Servers with versions older than 1.52 to versions 1.53 and higher</li> </ul>	1.55 on request
October 19, 2021	<ul> <li>are only possible if first an intermediate update to version 1.52 is uploaded.</li> <li>New mode: Encrypted connection (TLS-PSK) with Windows COM Port Redirector (version 3.92 and higher)</li> <li>Updates for Com-Servers with versions older than 1.52 to versions 1.53 and higher are only possible if first an intermediate update to version 1.52 is uploaded.</li> </ul>	1.54 on request
February 25, 2021	<ul> <li>Security updates</li> <li>SNMP: Private MIB activated (read only)</li> <li>Minimum value of the serial InQueue corrected</li> <li>Updates for Com-Servers with versions older than 1.52 to versions 1.53 and higher are only possible if first an intermediate update to version 1.52 is uploaded.</li> </ul>	1.53 on request
May 15, 2020	Update problem in versions 1.50 and 1.51 with activated logfile fixed	1.52 ZIP download
March 3, 2020	<ul> <li>Configuration upload under Win10 corrected</li> <li>GARPs with source and destination IP = 0.0.0.0 caused reset in DHCP mode</li> </ul>	1.51 on request
November 21, 2019	<ul> <li>New: Web-Based Management via HTTPS incl. certificate support</li> <li>BREAK signal processing optimized</li> <li>SNMP behavior MIB2 optimized</li> </ul>	1.50 on request
July 24, 2019	<ul> <li>Fixed possibly critical weakness in Web Based Management (VDE-2022-043)</li> <li>Display problems in Telnet and web configuration fixed</li> <li>Readout of the UART error register corrected</li> <li>New: TCP client option "Direct Connect"</li> </ul>	1.48 on request
March 21, 2018	<ul><li>Processing of BREAK signals adjusted</li><li>Support of a new flash type</li></ul>	1.45 on request

Date	Changes and comments	Revision
February 20, 2018	<ul> <li>Optimizations/corrections for Web-Based-Management</li> <li>Buffer handling optimized</li> </ul>	1.42 on request
June 29, 2017	<ul> <li>Optimized operation in DHCP environments with relay agents</li> <li>Security problem with Port 1094/TCP fixed</li> </ul>	1.41 on request
December 28, 2016	Optimized system response in noisy/slow network environments	1.40 on request
August 8, 2016	<ul> <li>Web Based Management: Optical corrections</li> <li>DHCP: Lease time calculation corrected</li> <li>TLS: TLS handshake optimized</li> </ul>	1.39 on request
April 12, 2016	Serial buffer handling optimized	1.37 on request
December 4, 2015	<ul> <li>NEW: Optional TLS encrypted Box-to-Box operation</li> <li>IP assignment with static ARP entry is possible in just 2 minutes after restart</li> <li>FTP server mode: Optimized closing of the connection</li> <li>Optimized DHCP behavior after link loss</li> <li>Configuration upload using WuTility works again</li> <li>Web page problem with split HTTP requests corrected</li> </ul>	1.35 on request
July 31, 2013	<ul> <li>New: Selectable detection of IP address conflicts (RFC5227)</li> <li>New: LED indication for boot-up and missing IP address</li> <li>Correction of Packet Options</li> <li>Correction of FTP Client mode</li> </ul>	1.31 on request
June 13, 2013	<ul> <li>Web page problem with IE10 corrected</li> <li>SLIP: Calculation of the routing subnet mask corrected</li> </ul>	1.30 on request
April 24, 2013	<ul> <li>Corrected subnet mask after switching to DHCP</li> <li>FTP-Client mode: Greeting message with Code 200 accepted</li> </ul>	1.29 on request
September 24, 2012	Behavior with flow control using CTS AND DSR corrected	1.27 on request
July 18, 2012	<ul> <li>Up-/download of the configuration corrected</li> <li>Optimized SLIP mode</li> <li>Mark/Space Parity implemented</li> </ul>	1.26 on request
November 15, 2011	<ul> <li>FTP Client mode with serial protocol corrected</li> <li>Mark/Space Parity implemented</li> </ul>	1.25 on request
June 14, 2011	Original version	1.24 on request



We are available to you in person:

Wiesemann & Theis GmbH Porschestr. 12 42279 Wuppertal Phone: +49 202/2680-110 (Mon.-Fri. 8 a.m. to 5 p.m.) Fax: +49 202/2680-265 info@wut.de

© Wiesemann & Theis GmbH, subject to mistakes and changes: Since we can make mistakes, none of our statements should be applied without verification. Please let us know of any errors or misunderstandings you find so that we can become aware of and eliminate them.

Data Privacy