W&I connects

Interfaces for TCP/IP, Ethernet, RS-232, RS-485, USB, 20mA, glass and plastic fiber optic cable, http, SNMP, OPC, Modbus TCP, I/O digital, I/O analog, ISA, PCI



Com-Server UL Model 58669

Current firmware

Date	Changes and comments	Revision
January 10, 2024	NEW: Operating mode Modbus/TCP-Gateway (connecting MB/RTU slaves to MB/TCP masters) DHCP: Problem with custom DHCP options fixed	1.58 ZIP download
	Updates for Com-Servers with versions older than 1.52 to versions 1.53 and higher are only possible if first an intermediate update to version 1.52 is uploaded.	

Older firmware

Date	Changes and comments	Revision
January 25, 2022	Client modes: Behavior of the Disconnect-Char corrected DHCP: Problem with DHCP relays corrected TCP: Behavior of TCP-Zero-Window optimized Updates for Com-Servers with versions older than 1.52 to versions 1.53 and higher are only possible if first an intermediate update to version 1.52 is uploaded.	1.56 on request
December 3, 2021	Security updates: WBM session management (VDE-2022-057) NEW: TCP Client mode with optional TLS-PSK encryption "Encrypted COM redirector" menu moved to "TCP Server" menu Updates for Com-Servers with versions older than 1.52 to versions 1.53 and higher are only possible if first an intermediate update to version 1.52 is uploaded.	1.55 on request
October 20, 2021	New mode: Encrypted connection (TLS-PSK) with Windows COM Port Redirector (version 3.92 and higher) Updates for Com-Servers with versions older than 1.52 to versions 1.53 and higher are only possible if first an intermediate update to version 1.52 is uploaded.	1.54 on request
February 26, 2021	Security updates SNMP: Private MIB activated (read only) Minimum value of the serial InQueue corrected Updates for Com-Servers with versions older than 1.52 to versions 1.53 and higher are only possible if first an intermediate update to version 1.52 is uploaded.	1.53 on request
May 15, 2020	Update problem in versions 1.50 and 1.51 with activated logfile fixed	1.52 ZIP download
March 23, 2020	Configuration upload under Win10 corrected GARPs with source and destination IP = 0.0.0.0 caused reset in DHCP mode	1.51 on request
November 21, 2019	New: Web-Based Management via HTTPS incl. certificate support BREAK signal processing optimized SNMP behavior MIB2 optimized	1.50 on request
July 24, 2019	Fixed possibly critical weaknesses in Web Based Management (VDE-2022-043) Display problems in Telnet and web configuration fixed Readout of the UART error register corrected	1.48 on request
July 25, 2018	Original version	1.45 on request



www.wui.ae

We are available to you in person:

Wiesemann & Theis GmbH

Porschestr. 12 42279 Wuppertal

Phone: +49 202/2680-110 (Mon.-Fri. 8 a.m. to 5 p.m.)

Fax: +49 202/2680-265

info@wut.de

© Wiesemann & Theis GmbH, subject to mistakes and changes: Since we can make mistakes, none of our statements should be applied without verification. Please let us know of any errors or misunderstandings you find so that we can become aware of and eliminate them.

Data Privacy