

Firmware:

Web-IO 12x Digital Input, 6x Digital Relay

Model 57634

57634(N) (recognizable by the existing firmware starting from v4.xx / March 2018)

Current firmware

Date	Changes and comments	Revision
January 8, 2020	<ul style="list-style-type: none"> Timeswitch - changed format in Google Calendar caught <p>To load this firmware, WuTility must be used in the newest version included!</p>	<p>4.04</p> <p>ZIP Download</p>

Older firmware

Date	Changes and comments	Revision
March 23, 2018	<ul style="list-style-type: none"> Firmware for the 0 series <p>To load this firmware, WuTility must be used in the newest version included!</p>	<p>4.02</p> <p>auf Anfrage</p>

57634(M) (for model with 2MB memory recognizable by the existing firmware starting from v3.xx / Feb 2011)

Current firmware

Date	Changes and comments	Revision
August 5, 2020	<ul style="list-style-type: none"> Network handling revised <p>To load this firmware, WuTility must be used in the newest version included!</p>	<p>3.77</p> <p>ZIP Download</p>

Older firmware

Date	Changes and comments	Revision
January 8, 2020	<ul style="list-style-type: none"> Timeswitch - changed format in Google Calendar caught <p>To load this firmware, WuTility must be used in the newest version included!</p>	<p>3.75</p> <p>auf Anfrage</p>
February 6, 2018	<ul style="list-style-type: none"> Network buffer management revised Time Switch - Cyclical appointment processing optimized 	<p>3.69</p> <p>auf Anfrage</p>
September 25, 2017	<ul style="list-style-type: none"> Firmware with SSL support in client modes Time Switch: Processing of UTC and local time optimized <p>To load this firmware, WuTility must be used in the newest version included!</p>	<p>3.68</p> <p>auf Anfrage</p>
February 3, 2017	<ul style="list-style-type: none"> Firmware with SSL support in client modes Time Switch: Optimized reloading of ics files <p>To load this firmware, WuTility must be used in the newest version included!</p>	<p>3.62</p> <p>auf Anfrage</p>
October 7, 2016	<ul style="list-style-type: none"> Firmware with SSL support in client modes Memory management revised <p>To load this firmware, WuTility must be used in the newest version included!</p>	<p>3.61</p> <p>auf Anfrage</p>
May 5, 2015	<ul style="list-style-type: none"> Firmware with SSL support in client modes Time Switch: Error handling when ics-files not present optimized System time synchronization corrected <p>To load this firmware, WuTility must be used in the newest version included!</p>	<p>3.50</p> <p>auf Anfrage</p>
February 25, 2015	<ul style="list-style-type: none"> Firmware with SSL support in client modes Login behavior optimized Timer function only after free licensing Download of online calendars via HTTPS revised Internal memory management newly structured <p>To load this firmware, WuTility must be used in the newest version included!</p>	<p>3.48</p> <p>auf Anfrage</p>
May 5, 2014	<ul style="list-style-type: none"> Firmware with SSL support in client modes Sending of SSL encrypted e-mails possible Online calendars can be opened via HTTPS 	<p>3.47</p> <p>auf Anfrage</p>

Date	Changes and comments	Revision
	<ul style="list-style-type: none"> • Administration optimized • Community string for SNMP traps configurable <p>To load this firmware, WuTility must be used in the newest version included!</p>	
August 7, 2013	<ul style="list-style-type: none"> • Socket interface: Processing of the "allout" command improved • Time-Switch: Processing of comma-delimited arguments optimized • Time-Switch: Blanks in front of the calendar URL are now ignored • SNMP: Setting of Enable flags expanded 	3.44 auf Anfrage
April 23, 2013	<ul style="list-style-type: none"> • Optimized processing of requests with transfer encoding: Chunked • Time-Switch: load option "no refresh" corrected • Time-Switch: Summer time-winter time switching without time server corrected • Time-Switch: BYDAY with +/-nWday corrected • External clock: Conversion to UTC • SMART page: Indexing of user tags corrected • HTTP Client: INPUT was also triggered by Pending TCP (fixed) <p>To load this firmware, WuTility must be used in the newest version included!</p>	3.42 auf Anfrage

57634 (for model with 1MB memory recognizable by the existing firmware up to v2.xx / Feb 2011)

Current firmware

Date	Changes and comments	Revision
February 6, 2018	<ul style="list-style-type: none"> • Network buffer management revised <p>To load this firmware, WuTility must be used in the newest version included!</p>	2.33 ZIP Download

Older firmware

Date	Changes and comments	Revision
August 13, 2013	<ul style="list-style-type: none"> • Smart page: Up-/Download ability added • SNMP: Setting of the alarm triggers optimized <p>To load this firmware, WuTility must be used in the newest version included!</p>	2.29 auf Anfrage
August 7, 2013	<ul style="list-style-type: none"> • Socket interface: Processing of the "allout" command improved • SNMP: Setting of Enable flags expanded <p>To load this firmware, WuTility must be used in the newest version included!</p>	2.30 auf Anfrage
August 10, 2011	<ul style="list-style-type: none"> • Send behavior for UDP alarms after link interruption improved • Basic initializing on bootup optimized <p>To load this firmware, WuTility must be used in the newest version included!</p>	2.28 auf Anfrage
April 6, 2011	<ul style="list-style-type: none"> • Optimizing of firmware upload in noisy environments <p>To load this firmware, WuTility must be used in the newest version included!</p>	2.27 auf Anfrage
October 13, 2010	<ul style="list-style-type: none"> • Boot-up behavior optimized <p>To load this firmware, WuTility must be used in the newest version included!</p>	2.26 auf Anfrage
September 29, 2010	<ul style="list-style-type: none"> • Problems with APP page eliminated <p>To load this firmware, WuTility must be used in the newest version included!</p>	2.25 auf Anfrage
August 19, 2010	<ul style="list-style-type: none"> • Box-to-Box - address management for NAT routing adjusted • Login for binary access revised <p>To load this firmware, WuTility must be used in the newest version included!</p>	2.24 auf Anfrage
February 5, 2010	<ul style="list-style-type: none"> • Update procedure changed • UDP - network buffer expanded • UDP - remote port can be set as desired • Negative logic for outputs configurable • State=TOGGLE introduced for socket command outputaces • DHCP: Device Name = DHCP Name <p>To load this firmware, WuTility must be used in the newest version included!</p>	2.23 auf Anfrage



Wiesemann & Theis
GmbH
Porschestra. 12
42279 Wuppertal
Phone: +49 202/2680-110 (Mon.-Fri. 8 a.m. to 5
p.m.)
Fax: +49 202/2680-265
info@wut.de

© Wiesemann & Theis GmbH, subject to mistakes and changes: Since we can make mistakes, none of our statements should be applied without verification. Please let us know of any errors or misunderstandings you find so that we can become aware of and eliminate them.

[Data Privacy](#)