

Firmware:

**LAN modem, 10BT****Model 58210****Module firmware (AT interpreter)****Current firmware**

Date	Changes and comments	Revision
March 25, 2003	<ul style="list-style-type: none"> <li>Command AT&amp;D3 modified</li> <li>A few internal modifications</li> </ul>	<a href="#">1.14</a> <a href="#">ZIP download</a>

**Older firmware**

Date	Changes and comments	Revision
March 6, 2002	<ul style="list-style-type: none"> <li>Support of additional serial character formats (parity, data bits, stop bits)</li> <li>Support of BREAK signals</li> </ul>	<a href="#">1.11</a> <a href="#">ZIP download</a>
June 21, 2001	<ul style="list-style-type: none"> <li>First version</li> </ul>	<a href="#">1.04</a> <a href="#">ZIP download</a>

**Basic firmware (TCP/IP stack)****Current firmware**

Date	Changes and comments	Revision
March 25, 2003	<ul style="list-style-type: none"> <li>A few internal modifications of the TCP/IP stack</li> </ul>	<a href="#">1.26</a> <a href="#">ZIP download</a>

**Older firmware**

Date	Changes and comments	Revision
October 1, 2002	<ul style="list-style-type: none"> <li>SNMP: Optimized walk over entire MIB</li> </ul>	<a href="#">1.25</a> <a href="#">ZIP download</a>