

Firmware:

Com-Server Highspeed 20mA

Model 58642

Current firmware

Date	Changes and comments	Revision
November 11, 2022	<ul style="list-style-type: none">• Security update: WBM session management• DHCP: Problem with DHCP relays corrected	1.78 ZIP download

[Show older firmware...](#)



We are available to you in person:

Wiesemann & Theis GmbH
Porschestra. 12
42279 Wuppertal
Phone: +49 202/2680-110 (Mon.-Fri. 8 a.m. to 5 p.m.)
Fax: +49 202/2680-265
info@wut.de

© Wiesemann & Theis GmbH, subject to mistakes and changes: Since we can make mistakes, none of our statements should be applied without verification. Please let us know of any errors or misunderstandings you find so that we can become aware of and eliminate them.

[Data Privacy](#)