

Firmware:

AT-Modem-Emulator**Model 58666****Current firmware**

Date	Changes and comments	Revision
July 24, 2019	<ul style="list-style-type: none"> Fixed possibly critical weaknesses in Web Based Management (VDE-2022-043) Readout of the UART error register corrected 	1.48 ZIP download

Older firmware

Date	Changes and comments	Revision
June 18, 2018	<ul style="list-style-type: none"> Connection opening optimized when using with mobile networks with delayed return direction 	1.46 ZIP download
March 21, 2018	<ul style="list-style-type: none"> Processing of BREAK signals adjusted Support of a new flash type Optimized operation in DHCP environments with relay agents Security problem with Port 1094/TCP fixed Optimizations/corrections for Web-Based-Management Buffer handling optimized 	1.45 ZIP download
December 28, 2016	<ul style="list-style-type: none"> Optimized system response in noisy/slow network environments 	1.40 ZIP download
August 8, 2016	<ul style="list-style-type: none"> DHCP: Lease time calculation corrected 	1.39 ZIP download
June 15, 2016	<ul style="list-style-type: none"> Various SSL/TLS optimizations 	1.38 ZIP download
April 12, 2016	<ul style="list-style-type: none"> Serial buffer handling optimized 	1.37 ZIP download
December 4, 2015	<ul style="list-style-type: none"> NEW: Optional TLS encrypted data connection Corrected behavior with CRLF as line end and dial-up via URL 	1.35 ZIP download
October 8, 2015	<ul style="list-style-type: none"> Corrected behavior for CRLF as line end of AT commands 	1.34 ZIP download
January 6, 2015	<ul style="list-style-type: none"> First version 	1.32 ZIP download