

Driver versions:

## Serial PCI cards

model 13011, 13410, 13411, 13421, 13610, 13611, 13621, 13812

### Current driver versions:

Date	Changes and comments	Driver revision
June 25, 2014	<ul style="list-style-type: none"> <li>Driver installation adapted</li> </ul> <p>Setup-based installation of all PCI and PCI Express cards Driver as <b>32-bit (x86)</b> and <b>64-bit (x64)</b> version for:</p> <ul style="list-style-type: none"> <li>Windows 2000</li> <li>Windows Server 2000</li> <li>Windows XP</li> <li>Windows Server 2003</li> <li>Windows Vista</li> <li>Windows Server 2008</li> <li>Windows 7</li> <li>Windows Server 2008R2</li> <li>Windows 8</li> <li>Windows Server 2012</li> <li>Windows 8.1</li> <li>Windows Server 2012R2</li> <li>Windows 10</li> <li>Windows Server 2016</li> </ul>	<p>8.30 <a href="#">ZIP download</a></p>

Date	Changes and comments	Driver revision
February 23, 2001	<ul style="list-style-type: none"> <li>First version</li> </ul> <p>Setup-based installation of all PCI cards for:</p> <ul style="list-style-type: none"> <li>Windows NT</li> </ul>	<p>3.00 <a href="#">ZIP download</a></p>

### Older driver versions:

Date	Changes and comments	Driver revision
June 4, 2013	<ul style="list-style-type: none"> <li>Uninstall optimized</li> </ul> <p>Setup-based installation of all PCI and PCI Express cards Driver as <b>32-bit (x86)</b> and <b>64-bit (x64)</b> version for:</p> <ul style="list-style-type: none"> <li>Windows 2000</li> <li>Windows Server 2000</li> <li>Windows XP</li> <li>Windows Server 2003</li> <li>Windows Vista</li> <li>Windows Server 2008</li> <li>Windows 7</li> <li>Windows Server 2008R2</li> <li>Windows 8</li> <li>Windows Server 2012</li> </ul>	<p>8.20 <a href="#">ZIP download</a></p>
October 18, 2012	<ul style="list-style-type: none"> <li>Setup-based installation of all PCI and PCI Express cards</li> </ul> <p>Driver as <b>32-bit (x86)</b> and <b>64-bit (x64)</b> version for:</p> <ul style="list-style-type: none"> <li>Windows 2000</li> <li>Windows Server 2000</li> <li>Windows XP</li> <li>Windows Server 2003</li> <li>Windows Vista</li> <li>Windows Server 2008</li> <li>Windows 7</li> <li>Windows Server 2008R2</li> <li>Windows 8</li> <li>Windows Server 2012</li> </ul>	<p>8.10 <a href="#">ZIP download</a></p>
14.12.2009	<ul style="list-style-type: none"> <li>Power management optimized</li> </ul> <p>Driver for <b>32-bit (x86)</b> and <b>64-bit (x64)</b> incl. certification</p> <ul style="list-style-type: none"> <li>Windows 9x (98 / ME)</li> <li>Windows 2000</li> <li>Windows XP / 2003 Server</li> </ul>	<p>7.00 <a href="#">ZIP download</a></p>

Date	Change/Introduction	Driver revision
June 3, 2009	<ul style="list-style-type: none"> <li>◦ Windows 7 / 2008 R2 Server</li> <li>• Scanning for devices (e.g. serial mouse) when Windows starts up can be turned off</li> <li>• Renumbering of ports optimized <ul style="list-style-type: none"> <li>◦ Windows x86: 98/ME/NT/2000/XP/2003/Vista/2008/7</li> <li>◦ Windows x64: XP/2003/Vista/2008/2008 RC2</li> </ul> </li> </ul>	<a href="#">6.53</a> <a href="#">ZIP download</a>
October 10, 2008	<ul style="list-style-type: none"> <li>• Baud rate wizard eliminated, baud rates are dynamically set <ul style="list-style-type: none"> <li>◦ Windows x86: 98/ME/NT/2000/XP/2003/Vista</li> <li>◦ Windows x64: XP/2003/Vista/2008</li> </ul> </li> </ul>	<a href="#">6.52</a> <a href="#">ZIP download</a>
August 19, 2008	<ul style="list-style-type: none"> <li>• Now also supports 64bit Windows <ul style="list-style-type: none"> <li>◦ Windows x86: 98/ME/NT/2000/XP/2003/Vista</li> <li>◦ Windows x64: XP/2003/Vista/2008</li> </ul> </li> </ul>	<a href="#">4.4.0.0</a> <a href="#">ZIP download</a>
October 19, 2005	<ul style="list-style-type: none"> <li>• Serial PCI card, all device revisions</li> </ul> <p>Windows 98/ME/2000/XP driver optimized: Installation of 1-port, 2-port, 3-port and 4-port cards possible</p>	<a href="#">1.33</a> <a href="#">ZIP download</a>
December 1, 2004	<ul style="list-style-type: none"> <li>• Serial PCI card, all device revisions</li> </ul> <p>Windows 2000/XP driver optimized: Driver options expanded</p>	<a href="#">1.32</a> <a href="#">ZIP download</a>
September 28, 2004	<ul style="list-style-type: none"> <li>• Serial PCI card, all device revisions</li> </ul> <p>Bugfix Windows NT driver: Installation problems if there is no local port.</p>	<a href="#">1.31</a> <a href="#">ZIP download</a>
September 29, 2003	<ul style="list-style-type: none"> <li>• Serial PCI card, all device revisions <ul style="list-style-type: none"> <li>◦ Windows 98/ME/2000/XP: Installation of 2-port and 4-port cards possible</li> <li>◦ Windows 2000/XP: Change in the numbering and deactivation of individual ports</li> </ul> </li> </ul>	<a href="#">1.30</a> <a href="#">ZIP download</a>
April 26, 2002	<ul style="list-style-type: none"> <li>• Serial PCI card, all device revisions</li> </ul> <p>Bugfix for Windows 2000 driver: Installation of an "unknown bridge device"</p>	<a href="#">1.22</a> <a href="#">ZIP download</a>
February 23, 2001	<ul style="list-style-type: none"> <li>• Serial PCI card, all device revisions</li> </ul> <p>Bugfix: Deactivation of the internal UART 8-bit local bus. The deactivation resulted in some cases in non-existent ports being registered.</p>	<a href="#">1.21</a> <a href="#">ZIP download</a>
November 3, 2000	<ul style="list-style-type: none"> <li>• Serial PCI card, all device revisions</li> </ul>	<a href="#">1.20</a> <a href="#">ZIP download</a>



We are available to you in person:

Wiesemann & Theis  
GmbH  
Porschestra. 12  
42279 Wuppertal  
Phone: +49 202/2680-110 (Mon.-Fri. 8 a.m. to 5 p.m.)  
Fax: +49 202/2680-265  
info@wut.de

© Wiesemann & Theis GmbH, subject to mistakes and changes: Since we can make mistakes, none of our statements should be applied without verification. Please let us know of any errors or misunderstandings you find so that we can become aware of and eliminate them.

[Data Privacy](#)