

Firmware:

## USB-Server Industry Isochron

Model 53642

### Current firmware

Date	Changes and comments	Revision
September 2, 2021	<ul style="list-style-type: none"><li>Optimized: Reset of USB devices by USB Redirector</li></ul>	2.17 <a href="#">ZIP download</a>

[Show older firmware...](#)



### We are available to you in person:

Wiesemann & Theis GmbH  
Porschestra. 12  
42279 Wuppertal  
Phone: +49 202/2680-110 (Mon.-Fri. 8 a.m. to 5 p.m.)  
Fax: +49 202/2680-265  
info@wut.de

© Wiesemann & Theis GmbH, subject to mistakes and changes: Since we can make mistakes, none of our statements should be applied without verification. Please let us know of any errors or misunderstandings you find so that we can become aware of and eliminate them.

[Data Privacy](#)