

Firmware:

Web-IO Digital 12xIn, 12xOut

Model 57630

57630(N) (recognizable by the existing firmware starting from v4.xx / March 2018)

Current firmware

Date	Changes and comments	Revision
January 8, 2020	<ul style="list-style-type: none"> Timeswitch - changed format in Google Calendar caught <p>To load this firmware, WuTility must be used in the newest version included!</p>	<p>4.04</p> <p>ZIP download</p>

[Show older firmware...](#)

57630(M) (for model with 2MB memory recognizable by the existing firmware starting from v3.xx / Feb 2011)

Current firmware

Date	Changes and comments	Revision
August 5, 2020	<ul style="list-style-type: none"> Network handling revised <p>To load this firmware, WuTility must be used in the newest version included!</p>	<p>3.77</p> <p>ZIP download</p>

[Show older firmware...](#)

57630 (for model with 1MB memory recognizable by the existing firmware up to v2.xx / Feb 2011)

Current firmware

Date	Changes and comments	Revision
February 6, 2018	<ul style="list-style-type: none"> Network buffer management revised <p>To load this firmware, WuTility must be used in the newest version included!</p>	<p>2.33</p> <p>ZIP download</p>

[Show older firmware...](#)